






Monitoring Dashboard Report P2122 Anchorsholme Park Storage Dewatering












Not Used



Notes:

1. Drawdown is below target

Panel 8

- 2. Flow is as expected and is stable
- 3. 9 No. pumps are operational as of 03/12/2015
- 4. Transducer installed in DW3 as of 26/11/15